



ERICO International Corporation
34600 SOLON RD
SOLON OH 44139
nvent.com

DECLARATION OF COMPLIANCE

REACH SVHC (EC 1907/2006)

In accordance with nVent's ESG commitments & article 33 of EC 1907/2006, we continuously strive to deliver products and services that reduce environmental & health & safety impacts when used for their intended purpose and in accordance with the performance conditions stated in our product documentation.

nVent declares to the best of our knowledge, based on supplier responses or our own ongoing due diligence, that our **Electrical Connections** (formerly known as Electrical & Fastening Solutions) products & packaging are manufactured in compliance with the REACH Regulation (EC 1907/2006). The presence of any substance specified in the REACH ECHA Substances of Very High Concern (SVHC) Candidate list (<https://echa.europa.eu/candidate-list-table>) in nVent products is set out in the table below. The Electrical Connections brands that are in-scope for this declaration are **Caddy, Eriflex, Erico & Lenton**.

Because we know regulations, standards and available information continues to evolve, nVent closely monitors, investigates, communicates, and exercises ongoing due diligence within our supply chain to ensure we continue to meet our obligations under the REACH SVHC Regulation. In the event that nVent becomes aware of the presence of a substance on the SVHC list, whether through investigation, testing, or notification from a supplier, we will promptly notify appropriate authorities under the regulation & amend the attached table to reflect the same.

Regards,

Tom Hurney

Director, Enterprise Product Compliance & Approvals



CADDY | ERICO | HOFFMAN | RAYCHEM | SCHROFF | TRACER

Notes:

- **Audit Instructions:**
 - If the **part number(s)** you are inquiring about **are not listed** in the last column **(Comments) in the table below**, then that product **does not contain any substance of concern**; therefore, it is considered **non-declarable**.
 - If the **part number(s)** you are inquiring about **are listed** in the last column **(Comments) in the table below**, then that part **does contain substance(s) of concern**; therefore, it is considered **declarable**.
- This online **Rev C** declaration is **the latest revision we have available**. The above table will be updated and a newer revision will be created as new information warrants.
- If you have any further **questions** about this declaration, **please email** Nichole.Knight@nVent.com

| Product Family | Product Name | SVHC Name | CAS No. | Comments |
|-----------------------------------------------------------|-----------------------------------------------------------------|-----------|-----------|-------------------------------------------------------------------|
| Air Terminal Base, Bracket Mount, Copper | Air Terminal Base, Bracket Mount, Copper, 3/8 UNC Thread | Lead | 7439-92-1 | The part number that is impacted is: LPC34938 |
| Air Terminal Base, Standing Seam, Imperial Thread, Copper | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC34812, LPC34838 & LPC34858 |
| Aircraft Grounding Receptacle Replacement Ball Stud | Aircraft Grounding Receptacle Replacement Ball Stud | Lead | 7439-92-1 | The part number that is impacted: B165RS |
| Aircraft Grounding Receptacle Replacement Cover | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: B167A & B167B |
| Aircraft Grounding Receptacle with Bar Attachment Point | Aircraft Grounding Receptacle with Bar Attachment Point, 7 1/4" | Lead | 7439-92-1 | The part number that is impacted: B167 |
| Compression Coupler for Copper-Bonded Ground Rod, Pointed | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: CC58, 158130 & CC34 |
| EB-12 Earthing & Neutral Busbar | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: 568610 & 568611 |

| | | | | |
|-------------------------------------------------------|------------------------------------------------------------------|----------------------------------------------|-----------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|
| EB-20 Earthing & Neutral Busbar | Earthing & Neutral Busbar, Brass, 20 Connections | Lead | 7439-92-1 | The part number that is impacted: 568662 |
| EB-36 Earthing & Neutral Busbar | Earthing & Neutral Busbar, Brass, 36 Connections | Lead | 7439-92-1 | The part number that is impacted is: 568620 |
| EB-44 Earthing & Neutral Busbar | Earthing & Neutral Busbar, Brass, 44 Connections | Lead | 7439-92-1 | The part number that is impacted: 568660 |
| EB-60 Earthing & Neutral Busbar | Earthing & Neutral Busbar, Brass, 60 Connections | Lead | 7439-92-1 | The part number that is impacted: 568661 |
| EB-168 Earthing & Neutral Busbar | Earthing & Neutral Busbar, Brass, 166 Connections | Lead | 7439-92-1 | The part number that is impacted: 568630 |
| EBC-133 Earthing & Neutral Busbars & Accessories | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: 568612 & 568613 |
| Female-Female Adaptor, Imperial Thread, Copper | Female-Female Adaptor, Imperial Thread, Copper, 3/8 UNC, 3/8 UNC | Lead | 7439-92-1 | The part number that is impacted: LPC2913F3F |
| Flexibar Supports | Multiple, therefore not listed | 6,6'-di-tert-butyl-2,2'-methylenedi-p-cresol | 119-47-1 | The part numbers that are impacted: 07930, 07931, 07932, 07933, 07934, 07935, 07821, 07822, 07823, 07824, 07825 & 07826 |
| Female-Female Swivel Adaptor, Imperial Thread, Copper | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC2823F2F, LPC2832F2F, LPC282L3F2F, LPC281L3F3F, LPC2813F3F, LPC285L5F5F, LPC2855F5F & LPC2842F5F |
| Female-Male Swivel Adaptor, Imperial Thread, Copper | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC2823F2M, LPC2832F2M, LPC2845F2M, LPC2813F3M, LPC281L3F3M, LPC2913F3M, LPC2822F3M, LPC2833F3M, LPC2822F3M & LPC2842F5M |

| | | | | |
|----------------------------------------------------------|-----------------------------------------------------------|----------------------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Ground Rod Clamp, U-Bolt Saddle, One Conductor | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: REP16120L, REC16120 & REC16120DK |
| Hex Head Bolt, Imperial Thread | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: A927F179 & A927F236 |
| Independent Support Clip | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: IDSTWB, IDS9TWB & IDS95TWB |
| Industrial Stack Air Terminal Bases, Brass | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPLC446 & LPLC433 |
| Industrial Stack Air Terminal Bases, Copper Lead Covered | Industrial Stack Base, Horizontal Cable Run, Lead Covered | Lead | 7439-92-1 | The part number that is impacted: LPLC431 |
| Industrial Stack Bonding Lug, Brass | Industrial Stack Bonding Lug, Brass, Lead Covered | Lead | 7439-92-1 | The part number that is impacted: LPLC451 |
| Industrial Stack Positioning | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPLC48034LG, LPLC48034SH, LPLC48058LG, LPLC48058SH, LPLC481SHP, LPLC482LG, LPLC482SH, LPLC49234, LPLC49258 & LPLC481LG |
| In-Line Air Terminal Bases, Copper | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC32112, LPC32138 & LPC32158 |
| Insulated Round Conductors | nVent ERICO Ericore Terminal Adapter | Lead | 7439-92-1 | The part number that is impacted: ERICOREAD15MM |
| Insulators | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: 07789, 07790, 07791, 07792, 07793, 07794, 07795, 07796, 07797, 07798, 07799, 07800, 07801, 07802, 07803, 07804, 07805, 07806, 07807, 07808, 07809, 07810, 07811 & 07812 |
| Neutral Busbar Mounting Kits | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: 568665 & 568666 |
| One Shots / PLUS One Shots | Multiple, therefore not listed | Bisphenol A & Formaldehyde | 80-05-7 / 50-00-0 | The part numbers that are impacted: VB21GCPA, VB21TCPA, VB21VCPA, VB22QCPA, VB21GCPB, VB21TCPB, VB21VCPB, VB22QCPB, VS21HCPA, VS21TCPA, VS21VCPA, VS22QCPA, VS21HCPB, VS21TCPB, VS21VCPB, VS22QCPB, RT2CRB2G, RT2CRB2L, RT2CRB2Q, RJ2CRB2G, RJ2CRB2L, RJ2CRB2Q, VB21GCPAPLUS, VB21TCPAPLUS, |

| | | | | |
|--------------------------------------------|----------------------------------------------|------|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | | | | VB21VCPAPLUS, VB22QCPAPLUS, VB21GCPBPLUS, VB21TCPBPLUS, VB21VCPBPLUS, VB22QCPBPLUS, VS21HCPAPLUS, VS21TCPAPLUS, VS21VCPAPLUS, VS22QCPAPLUS, VS21HCPBPLUS, VS21TCPBPLUS, VS21VCPBPLUS, VS22QCPBPLUS, RT2CRB2GPLUS, RT2CRB2LPLUS, RT2CRB2QPLUS, RJ2CRB1GPLUS, RJ2CRB2LPLUS, RJ2CRB2QPLUS, B100B152532, B100B4565 & B100B90115 |
| Rail Drilling & Grinding | Pedestal Rail Grinder Coupling | Lead | 7439-92-1 | The part number that is impacted: SBA1811 |
| Rail Four Post Terminal Block | Rail Four Post Terminal Block, with Hardware | Lead | 7439-92-1 | The part number that is impacted: B2700A2C1WH |
| Rebar Bonding Plate Cable Bond | Rebar Bonding Plate Cable Bond | Lead | 7439-92-1 | The part number that is impacted: LPLC468 |
| Right Angle Extension Adaptor, Copper | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC29638, LPC29612 & LPC29612A |
| Roof Ridge Air Terminal Bases, Copper | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC34738, LPC34758, LPC31212, LPC31512, LPC31558, LPC31258, LPC34712, LPC31238, LPC31538, LPC347L38, LPC304L12, LPC312L12, LPC30412, LPC31512, & PC31258 |
| Round to Round Connectors | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC513, LPLC441, LPLC443 & LPA598 |
| Standard Air Terminal Bases, Bronze; Brass | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC302TM16, LPC302M16, LPC30212, LPC30212V, LPC30412, LPC302L38, LPC304L38, LPC30258, LPC30258V, LPC30458, LPC30238, LPC30238V, LPC30438, LPC302L38, LPC302L38V, LPC30212, LPC30212V, LPC302L12, LPC302L12V, LPC30258, LPC302L58 & LPC302L58V |
| Standard Air Terminal Bases, Copper | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC304L38, LPC304L58 & LPC30458 |
| Standing Seam Clamps | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPA814 & LPC814 |

| | | | | |
|-------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|------|-----------|------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Through Roof Assemblies, Copper | Through Roof Assembly, Air Terminal, Swivel to Parallel Conductor, Copper, Stainless Steel 18-8 (EN 1.4305), 3/8 UNC Thread | Lead | 7439-92-1 | The part number that is impacted: LPC62838 |
| Through Roof/Wall Connectors | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC66418, LPC66424, LPC664A18 & LPC664A24 |
| 2G9 Twist Clip for Track Lighting, Narrow Grid | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: 2G9S10WB & 2G9WB |
| 4G8 Twist Clip for Track Lighting | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: 4G8WHWB & 4G8WB |
| Sub-family: AI, TWIST ON TRACK LIGHT CLIPS & T-GRID HANGERS | NUT,HEX,#8-32 BRASS,100/BAG | Lead | 7439-92-1 | The part number that is impacted: A928B048P100 |
| Sub-family: FH, HEAVY DUTY STACK | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPLC458X34, LPLC458X58, LPLC492CP, A927F097, LPLC458P, LPLC458X34 & LPLC458X58 |
| Sub-family: F5, CONVENTIONAL AIR TERMINALS | COUPLER,MALE,TERMINAL,AIR | Lead | 7439-92-1 | The part number that is impacted: LPC27758 |
| Sub-family: F6, CONVENTIONAL BASES | Multiple, therefore not listed | Lead | 7439-92-1 | The part numbers that are impacted: LPC30038, LPC300L38, LPC31438, LPC302T12. LPC302TL12, LPC34312. LPC302T58, LPC302TL58, LPC302TL38, LPC34358 & LPC34338 |

Last Updated: **05/28/2025**

**REACH Candidate List Updates (after the date listed above): We need more time to complete the needed due diligence on these. We apologize for any inconvenience this may cause. Thank you for your understanding & patience.*